



Silk Error Details: PIC16F876A LCD Satellite Tracker & Rotor Controller

ST2 – 0816 U4 mounting / SILK ERROR:

U4 must be mounted on other side (Solder Side) of the board as detailed and explained in two pictures below:



73s / Dinesh Gajjar / 29th November 2016

For more details, please visit Project Page: <http://www.foxdelta.com>